

STEPPING MOTORS TYPE 42BHH48W-200-24

SPECIFICATIONS				WIRING DIAGRAM
STEP ANGLE	1.8°±5%	VOLTAGE	3.0V	<p>红 A RED</p> <p>绿 C GRN</p> <p>B YEL 黄</p> <p>D BLU 蓝</p>
NO. of PHASE	2	CURRENT/PHASE	2.0A	
Inultion Resistant	100MΩ(500VDC)	INDUCTANCE/PHASE	3.0±20%.mH	
Ambient Temperature	-35~40℃	RESISTANCE/PHASE	1.5±10%.Ω	
Operate_Temperature	110℃ Max	HOLDING_TORQUE	4.3kg.cm	
WEIGHT	0.24kg Max			

FIGURE

UNIT:mm

